




ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2403



mitsubishi

MD184230,MD158409
MD334558 MD152648
MD179787, MD192126
MD163599, MD310298
DIAMOND F-608 F-648

EKIL - 2501



CHRYSLER 4751253,5234210,
5252577,4797293,
90048-52091-000

GM 19017110

DELCO C506

LUCAS DMB968

DODGE TRUCK 90-95

JEEP 91-97

PLYMOUTH TRUCK 91-95

EKIL - 2502



JEEP 4762312

JEEP 91-93

EKIL - 2503



FORD 9 220 061 726

FORD 9 220 061 710

FALCON EA , EB

EKIL - 2503A



CHRYSLER

56028172,56028172A

56028172B

DODGE TRUCKS & VAN 98-2001

JEEP 98-2001

LUCAS DMB963

EKIL - 2503C



CHRYSLER

56028172,56028172A

56028172B

DODGE TRUCKS & VAN 98-2001

JEEP 98-2001

LUCAS DMB963

EKIL - 2503B



NISSAN 86-88

EKIL - 2504



DAIHATSU
DIAMOND

90048-52101-000
F-718

EKIL - 2504A



SUZUKI

33410-56B10

33410-56B10



GM 96064792

CHEVROLET 93-94

GEO 93-94



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2504B



DAIHATSU 90048-52080-00
SUZUKI 33410-62E10
 90048-52094
 33410-50G10
 F-609
 33410-60ECO
 33410-62E10

EKIL - 2504C



DELPHI: CE10514-1281
LAND ROVER NEC100800
LAND ROVER NEC100800L
LAND ROVER NEC 000 12(L)
 NGK 48125

EKIL - 2505



DAIHATSU 90048-52109-000
DIAMOND F-714

EKIL - 2506



DAIHATSU 90048-52110 (S91)
DIAMOND F-614
 90048-52096
DIAMOND F-076, F-614

EKIL - 2507



DAIHATSU 90048-52056
 90048-52096-000
 90048-52096
DIAMOND F-076, F-614

EKIL - 2508



SUZUKI 33410-56B10
GM 96064792
CHEVROLET 93-94
GEO 93-94

EKIL - 2509



TORCH 5019

EKIL - 2601



DAIHATSU 90048-52056,
 90048-52059 90048-52091
MAZDA F210-18-100, F210-18-100B
 F211-18-100A, E7GY-12029A,
 EFGZ-12029A
SUZUKI 33410-64B10
MITSUBISHI J2T00572, J2T00772,
 J2TO0972
DIAMOND F-095, F-092, F-065

EKIL - 2602



FORD E8GY-12029B,
 E92Z-12029B FO2Z-12029B, FO2Z-
 12029A, DGE437, DGE439,
 DGE443
MAZDA F210-18-100, F210-18-100B
 F211-18-100A, E7GY-12029A,
 EFGZ-12029A
SUZUKI 33410-64B10
MITSUBISHI J2T00572, J2T00772,
 J2TO0972
DIAMOND F-095, F-092, F-065



EKIL - 2603



DAIHATSU: 19080-Z9121
GM: 19080-Z9121
 100297-0860 19080-87703
DAIHATSU : -2001



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2604



mitsubishi MD0339027
DIAMOND F-809

EKIL - 2604A




mitsubishi motors
MD338169
MD339027

EKIL - 2605



mitsubishi MD111950, MD114994
MD104698
GM 19017112, E-569, F-088, 605043
HYUNDAI 27301-02502, 27301-22000
27301-24520 27301-24510, 27301-24000
BOSCH 0986221006
LUCAS DMB846

EKIL - 2506A



HYUNDAI 27301-02502
BOSCH 0986221006

EKIL - 2605B



HYUNDAI 27301-32810,
27301-32820,
27301-32800
mitsubishi MD111950
MD104696
DIAMOND F-089
BOSCH 0986221012
LUCAS DMB841
BERU 0040100261, ZS261

EKIL - 2606



KIA KK137-18-10X,
KK137-18-10XC
KK137-18-100
HYUNDAI 27310-35010,
NISSAN 22433-12P01,
22433-12P11, 22448-03E01,
22448-03E11, 22433-V4410
mitsubishi MD098964,
MD104696 MD113551,
MD131711, MD141044

EKIL - 2606A



mitsubishi MD098964, MD104696
MD113551, MD131711, MD141044
MD160532, MD166146, 19017117
KIA KK137-18-10X,
KK137-18-10XC, KK137-18-100
NISSAN 22433-12P01
22433-12P11 22448-03E01
22448-03E11 22433-V4410
HYUNDAI 27310-35010,

EKIL - 2606B



HYUNDAI 33410-A-78B00

EKIL - 2607





mitsubishi MD102315,
MD120167, MD177230,
MD120618, MD107864,
19017127, MD170090,
805023, DLJ219

EKIL - 2610



SUZUKI 33410-85120,
33410A60D30
DIAMOND FTM-063GT,



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2701



VW/AUDI 330905115A
BOSCH 0221502007,
0221502008
SUZUKI 330 9005 115A
BERU 0040100280, ZS280

EKIL - 2605C



HYUNDAI BKIGC02
KIA OK9A2-18-10XB

EKIL - 2702



RENAULT 7700749450,
7700858138, 7702218697
BOSCH 9220081505
BERU 0040100250, ZS250
CHAMPION BAE504L, AMC504L
SAGEM 2526034
LUCAS DLB301

EKIL - 2702M



RENAULT 7401 275 174
VOLVO 1275174,
1367777, 3507934
BOSCH 0221 601 012
BERU 0040102037
LUCAS DMB892

EKIL - 2703



BOSCH 9220081504,
F000ZS0105
BERU 0040100314 ZS314
AUDI/VW 377905105D

EKIL - 2703M



BOSCH 9220 081 506
9220 087 034
F000 ZS0 104
VW 377 905 105B

EKIL - 2710



VW 867905104B
VOLKSWAGEN GOLF 92-97
VW JETTA (SUDAMERIKA ME) 92-97
GOLF(SUDAMERIKA MEXICO) 92-97

EKIL - 2710M3



AUDI/VW 357905104, 701905104
701905104A, 867905104B, 867905104A
BOSCH 0221601001, 0221601002,
0221601006, 0221601007, 0221601003,
0221601004

EKIL - 2710M6




AUDI/VW 867905105A,
701905104, 867905351,
701905104A, 547905104
BOSCH 0221601001, 0221601002,
1227030049
VW/PASSAT 1.6, 1.6i, 1.8i
POLO 1.0, 1.0i, 1.3, 1.3i
SEAT 701 905 104A

EKIL - 2711



AUDI/VW 357905104, 701905104
701905104A, 867905104, 867905104A
867905105A, 867905352
BOSCH 0221601001, 0221601002,
1227030051, 1227030052
SEAT 867905104
LUCAS DLB708
STANDARD UF-96


Ignition Coil
Cluster Ionizer
Solenoid
Auto Parts
EKIL - 2711M3


AUDI/VW 867905104,
867905104A, 867905352,
701605104, 701605104A,
867905105A
BOSCH 0221601001, 0221601002
SEAT 867905104

EKIL - 2711M6


AUDI/VW 867905105A, 701905104A,
701905104
BOSCH 0221601001, 0221601002

EKIL - 2720


AUDI/VW 6N0905104, 867905104,
040100025, 867905104A
BOSCH 1227022030, 1227030030
SEAT 6N0905104, 867905104
SKODA 004050016, 6N0905104

EKIL - 2720M3


AUDI/VW 6N0905104, 867905104,
867905352, 867905104A
BOSCH 0221601003, 0221601004
0221601005, 1227030030, 1227022030
SEAT 6N0905104, 867905104
SKODA 004050016
LUCAS DAB 427
VALEO 245092

EKIL - 2720M6


AUDI/VW 701905104,
701905104A, 867905105A
BOSCH 0221601001,
0221601002, 986221002
SEAT 867905105A
LUCAS DAB430

EKIL - 2723


BERU 9741 102 000 0000
BENZ 000 150 1680

EKIL - 2723A


VW 021905106, 021905106A,
31088001
FORD 1008464, 95VW12029AA
MERCEDES 0031585001
A0031585001
BOSCH 0986221015
LUCAS DMB895
BERU 0040402004

EKIL - 2723B



VW 021905106C, 021905106B
BERU 0040100007, ZS007
STANDARD UF-338
LUCAS DMB921

EKIL - 2801


PEUGEOT 597045, 106205606
CITROEN 597045, 96035284,
9603528480
SAGEM 2526026, 2526026A
VALEO 245039, CD330
LUCAS DLB233
BOSCH 0986221029
BERU 0040100249, ZS249
MARELLI BAE507BK, 06705738010
6705754010

EKIL - 2801A


PEUGEOT 597047
CITROEN 597047, 96041378
FIAT 9604137880
SAGEM 2526024, 2526024A
VALEO 245038, CD326,
2526024, 2526024A
DUCELLIER 2526024A
BERU 0040100258, ZS258



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2802



FIAT 7553120, 7746153, 7646974,
7588435, 4460205
BOSCH 0986221028
VAELO 245052
MARELLI BAE506F, 60705606010
LUCAS DMB826

EKIL - 2803



FIAT 7553120, 7746153, 7646974,
7588435, 4460205
BOSCH 0986221028

EKIL - 2804A



GM 90449739, 90510386
OPEL 1208003, 1208054, 1208070
SAGEM 2526049, 2526049A
VELEO 245042, CD338
BOSCH F000ZS0111
BERU 0040100253, ZS253
DUCELLIER 2526049, 2526049A
DELCO REMY 3474233, 3474283

EKIL - 2805



JAGUAR DAC4608
MARELLI BAE504DK
LUCAS DMB943
JAGUAR 91-95

EKIL - 2805A



FIAT 07588435, 07646975,
07753777, 7646975,
0446025
FERRARI 115013, 1150131A
SAGEM 2526031A
MARELLI
BAE504D, BAE209B, 60705404
060705404010, 060705406010,

EKIL - 2806



PEUGEOT 597043, 205309405
CITROEN 597043, 96010513,
97530780
DUCELLIER 520073, 520073A
LUCAS DLB205
VAELO 520073, CD308
BOSCH F000ZS0114
BERU 0040100247, ZS247

EKIL - 2806A



CITROEN 97531206
PEUGEOT 597042, 205309405
VAELO 245001, 2526009, CD321
SAGEM 2526009, 2526009A
BOSCH F000ZS0113
BERU 0040100257, ZS257
LUCAS DLB206
MARELLI BAE507AK, 60705701
60705738010, 60705738

EKIL - 2807A



OPEL 1208002, 1208004,
1208036, 1208048
GM 03474232, 03474282,
90449740, 90510387
SAGEM 2526050
VAELO 2526050, CD339, 245043
LUCAS DLB703, DLB305
BERU 0040100252, ZS252
BOSCH F000ZS0112
DELCO REMY 03474232, 03474282

EKIL - 2808A



FIAT 7582152, 7663177,
7698431, 7746152,
7746154
VAELO 2256030, 245149,
CD328
SAGEM 2526030
MARELLI BAE506, BAE506D,
60705604, 60705604010,
BAE506C, BAE506G,
BAE506A
BOSCH 0986221027
BERU 0040100244


EKIL - 2809



RENAULT 7701031135,
33002299, 12336238
MARELLI BAE504B
VAELO 245054, DMB823
SAGEM 2526023, 2526048
BOSCH F-000-ZS0-115
BERU 0040100316, ZS316
LUCAS DLB204, DMB823
VOLVO 3287677-3



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 2809M



RENAULT 7700722070, 7700732263,
7700749146, 7700852093, 7700852662
RENAULT R9, R11, R19, R21, R25
PEUGEOT 405/309
SIEMENS S102020001C, S102030002A

EKIL - 2810



BOSCH 0221504461
LADA VA06-0001,
2112-3705010-10
1220703202

EKIL - 2811



BOSCH 0221503001
LADA 4715.3705

EKIL - 2812



ROVER GCL201, NEC100630
VALEO 245071, 2526073
BREMI 11935
DUCELLIER 2526073A

EKIL - 2910



FORD F5FU-12029-AA
FORD ESCORT VW
POINTER , GOL ,VERONA
547905105B

EKIL - 3001



GM D555, D539, D540,
D545, D576, 1103608,
1103646, 1103662
10467067, 01103759,
1103759, 1103744,
1103745, 1103746
10468391, 10472401,
10497771
ISUZU 8-10468-391-0,
8-10472-401-0
8-01103-830-0
LUCAS DMB970

EKIL - 3101



GM D524, D531, D536
876209, 1985474, 1988908
BUICK MODELS V6/V8 74-90
CADILLAC MODELS V6/V8 75-95
PONTIAC MODELS V6/V 74-90
CHEVROLET/GMC TRUCK 75-76;77-85
GM TRUCK 77-86
WIRES--- RED AND WHITE

EKIL - 3101A



GM D530, D523, D532,
8131936, J8131936,
1875894, 1985473
10497132, CONP 12029A,
DGG-419
CHEVROLET TRUCK 74-89
CHECKER MOTORS 75-82
GMC TRUCK 74-89 WIRES-RED AND
YELLOW

EKIL - 3102




GM D525, D527, D528, D529
1187847, 8134003, J8134003,
1115444, 1115445, 1115447,
1115449, 1115460, 1115448,
1115455, DGG-222, DGG-322,
DGG-421, 5-73, 5-74
GMC TRUCK 75-77;82-84
CHEVROLET TRUCK 75-77;82-84
OLDSMOBILE 75-77;81-84

EKIL - 3103



FORD E1EF 12029 AA,
E2EF 12029AA, E2FZ12029A,
E3EF 12029 AA, E3FZ 12029 A,
E73F 12029 AA ,E73F 12029 AB,
E73Z 12029 A, F-1953,
1694979-C1, F515-18-10X,
DG-325,DG-325A,DGE-325ADP,
DG-434
MAZDA, ZZM1-18-100, ZZM4-18-100


Ignition Coil
Cluster Ionizer
Solenoid
Auto Parts
EKIL - 3104


GM 19017000, E-533
TOYOTA 90919-02106,86-90
DENSO 0297004790

EKIL - 3105


GM 19017135, E-558
TOYOTA 90919-02154
TOYOTA 83-93

EKIL - 3106


RENAULT 7702218586
RENAULT 19 1.6 (HASTA 1995)

EKIL - 3107


BOSCH 9220081505
RENAULT 7700749450
RENAULT 191.6Lts DESDE 1995
 9(ULTIMA SETIE),
 TRAF IC-TWINGO
GM 1115467, 8A09
DAEWOO 01115467, 115467,96165049
LUCAS DMB894

EKIL - 3107A


RENAULT 7702205459
RENAULT 191.6Lts DESDE 1995
RENAULT 9(ULTIMA SETIE)
MARELLI 06070540910,
 60705409, BAE504L

EKIL - 3201A


GM 1115467, 8A09
DAEWOO 01115467, 115467,96165049
LUCAS DMB894

EKIL - 3201B


GM D-535,D-537,D-544,D-548,
 D-560,D-573
 1115315, 1115317, 1115468,
 1106013, 10477944 ,1841856
 1871561,19005205,813597,
 814541,820133,823294,
ISUZU 8011153150, 8011154660
DIAMOND F-616
OLDSMOBILE 85-97
BUICK 85-88 91-95
ISUZU 87-94

EKIL - 3202



GM D-577, 10489421
ISUZU 8-10489-421-0
CHEVROLET TRUCK 96-99
GMC TRUCK 96-99
PONTIAC 96-97
OLDSMOBILE 96-97

EKIL - 3203


GM D-535, D-537, D-544D-560,
 D-573 , 1115315, 1115317,
 1115466 , 1115468,
 1115491 , 10477208 , 83501871
 8983501871
ISUZU 8011153150, 8011154660
 806673T , 817378T
CHEVROLET TRUCK 85-97
GMC TRUCK 85-97

EKIL - 3203A


GM D-535,D-537 D-544
 D-560,D-573, 1115315,
 1115317, 1115468,
 10477208,1115466,
 1115491, 1106013,
 10477944 ,1841856,
ISUZU 8011153150,
 8011154660
DIAMOND F-616
AMC 8983501871
CHRYSLER 83502140



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 3203B



GM D-535 , D-537 , D-544 ,
D-560 , D-573, 1115315 ,
1115317 , 1115466 , 1115468
1115491, 10477208, 83501871,
8983501871
ISUZU 8011153150, 8011154660
806673T, 817378T

EKIL - 3301



TOYOTA 90919-02135, 90919-02136,
90919-02139, 90919-02152,
90919-02196
DENSO 0297005430
GEO 94840127
GM 94840127 94847392

EKIL - 3302



GM 94840127, 94847392
NIPPON DENSO 029700-5430
TOYOTA 90919-02196
BOSCH F000ZS0117

EKIL - 3401



HONDA 30500-PAA-A01,
30500-POA-A01
30500-POH-A01
30500-PCA-003,
30500-PDA-E01
ISUZU 5862061610, 5862071980
LUCAS DMB876

EKIL - 3402



HONDA 30500-POA-A01,
30500-POH-A01
30500-PCA-003,
30500-PDA-E01
30500-PAA-A01
HITACHI CM1T-228
HONDA ACCORD -2001
ISUZU 582061610,
5862071980,
ROVER GCL207 NEC100750

EKIL - 3403



GM 19017118, E-545
HONDA 30510-PT2-006,
30510-P73-A01
30510-P73-A02
ROVER GCL195, NEC100530
LUCAS DLJ313
BOSCH F000ZS0116

EKIL - 3404



NISSAN 22433-OM200,
22433-F4302
HITACHI CM1T-227
TOYOTA 90919-02200
BERU 0040100326

EKIL - 3405



HITACHI CM1T-231

EKIL - 3406




HITACHI CM1T-215

EKIL - 3407



HITACHI CM1T-216



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 3408



HITACHI CM1T-216

EKIL - 3409



HITACHI CM1T-230
NISSAN 22433-4M000,

EKIL - 3601,3406



Honda 30500-PT0-005
30500-P01-005, 30500-PM3-005, 30500-PM3-015
Hitachi CM1T-209B, CM1T-217,
Honda Civic, CM1T209A
LUCAS DMB834
BREMI 11726

EKIL - 3701



TOYOTA 90919-02164
GM 94404545, 94853695
ISUZU 8-94404-545-0
LUCAS DLJ431
BOSCH F000ZS0117

EKIL - 3702



TOYOTA 90919-02163
GM 94855502
LUCAS DMB949
BOSCH F000ZS0121

EKIL - 3704



TOYOTA 90919-02197, 90919-02208
E-546, 19500-74040, 19500-74050,
DENSO 0297007050, 100297-0450
LEXUS LS400 4.0i V8

EKIL - 3705



TOYOTA 1908013030, 90919-02197,
90919-02208
DAIHATSU 9008019004
DENSO 0297007690

EKIL - 3707



TOYOTA 90919-02175, 90919-02188,
90919-74030
DENSO 0297006450, 0297006451
297006841

EKIL - 3708




SUZUKI 33410-57B10
SUZUKI 33410-80C10,
33410-57B10-000
LUCAS DMB832

EKIL - 3709



TOYOTA 90919-02185 1907136,
E-559 90919-02185T
DENSO 0297006820
LEXUS 400 88-92
STABDARD UF-71


Ignition Coil
Cluster Ionizer
Solenoid
Auto Parts
EKIL - 3710


TOYOTA : 19070-74170,
19500-74090,
19500-74091,
19500-74100,
90919-022069,
90919-02207
LUXUS 92-97

EKIL - 3801


GM D-550 D-574 D-583
10457109, 10472748, 10474481,
10497477
BUICK 88-98
OLDSMOBILE 87-98
CHEVROLET 90-98
PONTIAC 88-99

EKIL - 4001


GM 19017120, E-547,
805054, DLJ453
ISUZU 8-94338-923-0,
8-94371- 838-0,
8-94449-494-1
GM 94371838
OPEL 4304227

EKIL - 4002


GM 19017022, E-354, E-534, 80 5017,
DLJ109, 94136766
NISSAN 22433-12P00, 22433-12P01
22433-12P10, 22433-12P11,
22433-18R10, 22448-18R10, 22488-61A00,
22488-61A10, 22448-89W00, 22448-
89W10, 22448-90W00,
22448-90W10, 22433-42L10
ISUZU 8-94136-766-0
HITACHI CM1T-205
DAEWOO 96320818,96336522,
KIA AA100 181 100B

EKIL - 4003


GM 19017173 , E-571 , DG-450 ,
DG-464 , 805045 , DLJ127
NISSAN 22433-0B00,22433-0B000,
22433-0B001 , 22433-0B010 ,
22433-51J10 , 22433-53J20 ,
22448-19B61 , 22448-0C801 ,
22448-65E00 , 22448-56E11 ,
FORD 1953302, 1953306,F3XA-12029-AA,
F3XY-12029-A, F5XZ-12029-AA
LUCAS DLJ300

EKIL - 4004


GM 19017126, E549 805055,
DLJ127 22433-03G01
NISSAN 22433-03G10 ,22433-03G11
22433-10G10 , 22448-03G01,
22448-03G11 , 22488-04G01 ,
22448-04G11 , 22448-10G00,
22448-10G10, 22448-11G00,
22448-19B10, 22448-11G10,
22448-19B10, 22448-D4512,
22448-29R10, 22448-D4501,
22448-D4511 22448D4513 ,

EKIL - 4006


NISSAN 22433-53F00 ,
22433-55Y00 22433-65Y10 22448-1C701,
22448-37J10, 22448-37J20

EKIL - 4006A



MAZDA B6S7-18-10XA, B6S7-18-10XB
B6S8-18-10X B6S8-10-XZ,10917121
FORD DGE447 DGE 448 FICZ-12029-A
FICA-12029-A FOBZ-12029-A FOC6-
12029-AA , B6S7-18-100,
MAZDA F2G8-18-10X, F2G9-18-10X,
B6S8-10-10XA, F511, 323 90-95
BOSCH F0005X1175

EKIL - 4006B


MAZDA G601-18-10X,G601-18-100
G602-18-10X,G622-18-10X,
G622-18-10X, G623-18-10X,
JE48-18-10XB, F-558,805044,
DLJ232,G622-18-100
B121-18-10X, B541-18-10XA,
JE49-18-10XB G607-18-10X,
JE48-18-100B, G607-18-100
KF01-18-100, KF01-18-10X
B542-18-10XA, G607-18-100,
BREMI 11920
LUCAS DMB942

EKIL - 4006C


DIAMOND FTM-558-A3



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 4210



CHAMPION BAE800B
FIAT 7626232,7672018,7692473
 46543562,46548037,46790073
MARELLI
 060708038010,060780002010
 60708038,BAE800AK,BAE800DK BAE800B
LUCAS DLB314
BOSCH F000ZS0103

EKIL - 4210A



MARELLI BAE800EK,BAE801EK
 060708049010,060708149010
RENAULT 7700107269
SEAT SE 028915.000B
BOSCH 0986221033

EKIL - 4210B



RENAULT 7700854306
MARELLI BAE801AK, 60708138
LUCAS DMB802

EKIL - 4210C



FACET 9.6176
BERU 0040100318
RENAULT 7700854307 7700872692
MARELLI BAE801BK

EKIL - 4210D



FACET 9.6177
BERU 0040100319
RENAULT 7700858320 , 7700872693
MARELLI BAE801CK

EKIL - 4211



RENAULT 7701041607,7700863020,
 7700850999,7700865923
SAGEM 2526051A,2526110A
VALEO 245066,245076
VOLVO 70863020-7,70863020
BOSCH 0986221030
LUCAS DMB404

EKIL - 4211A



RENAULT 7700863021,7701041608
SAGEM 25603K00429,2526052A
 2526111A, 7700850999
VOLVO 70863021-5,70863021
VALEO 245067
BOSCH 0986221031
LUCAS DMB405

EKIL - 4212



RENAULT 7700100589
SAGEM 2526114A
BOSCH 0986221025
BREMI 11722
LUCAS DMB407

EKIL - 4212A



RENAULT 7700100643
SAGEM 2256115A
BOSCH 0986221026
BREMI 11723
LUCAS DMB405
BERU 0040100243


EKIL - 5001



BOSCH 0221506002,0221506003
 0221506444,0221506445
BERU ZS340
DAEWOO 0001587003,0001587503
MERCEDES 0001587003,0001587103
BENZ SLK230
VOLKSWAGEN 00A905105
FACET 9.6216



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 5002



BOSCH 0221506444
BERU 0040100295,ZS295
MERCEDES-BENZ
 A0001587003,A0001500280
DAEWOO 000158703
VW 00A905105

EKIL - 5003A



BOSCH 0221502435
BERU 0040100299,ZS299
MERCEDES-BENZ
 0001586503,A0001586503
BMW 1990-1994,1995,1993-1994,
 1991-1992

EKIL - 5003B



BOSCH 0221501374,0221502433
BERU ZS298,0040100298
MERCEDES-BENZ
 0001585803,0001585603,600SL
 E420,E500,E600,SL500,SL600
PORSCHE 95960250200

EKIL - 5004



BOSCH 0221505437,0221505438
MERCEDES-BENZ
 0001500480,0001500580
 0001586803,A0001500480
 A0001586803
LUCAS DMB872
BERU 0040103007

EKIL - 5005



VW/AUDI 058905101,058905105
SEAT 058905105
SKODA 058905105
LUCAS DMB403
BREMI 11869
BOSCH 0986221011
BERU 0040100013

EKIL - 5006



GM 10457730,19005218
 D-585
STANDARD UF-262
WELLS C1251
CADILLAC 2002-2004 ESCALADE
 2003-2004 ESCALADE ESV
 2002-2004 ESCALADE EXT
CHEVROLET 2002-2004 , 1999-2004
 2003-2004, 2000-2004

EKIL - 5007



GM
 E579A,E580A,E581A
SUBARU
 SVX4X4 H6 3.3L 1994
 SVXL H6 3.3L 1994-1997
 SVXLE H6 3.3L 1994
 SVXLS H6 3.3L 1992
 SVLSI H6 3.3L 1994-1995
 SVXLSL H6 3.3L 1924-1994

EKIL - 5008



FIAT LANCIA 46403328
BOSCH 0221504006
BERU 0040100310
DELPHI CE20035-12B1
STANDARD 12743
LUCAS DMB863

EKIL - 5009



GM 12568062
ISUZU 8125680620
STANDARD UF-303
BUICK RAINITER 05-04
CHEVROLET LIGHT TRUCK
 06-04
GMC LIGHT TRUCK CANYON
 06-04
HUMMER H3 06


EKIL - 5010



BOSCH 12227030059
ALFA ROMEO 7793212
FIAT 7793232



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 5011



FIAT 46755605
ALFA ROMEO 46755605
BOSCH 1 227 030 071
BERU 0040100361

EKIL - 5011A



FIAT 46469863 (2 PINS)
ALFA ROMEO 46469863
BOSCH 1227030062

EKIL - 5012



BERU 0040100346
PEUGEOT 597055
SAGEM 2526084
PSA 96213181
CITROEN 96213181
PEUGEOT 306

EKIL - 5016



GM 19058125
GM 12573190
GM 10457730
IC-77 RUF414

EKIL - 5017



BERU
0 040 172 648
UF-413 12570616
H6T55271ZC

EKIL - 6001



MAZDA H3T024
MAZDA 155852
DIAMOND F-696,618393
MAZDA 1984
MITSUBISHI 1992-1996

EKIL - 6002



MITSUBISHI H3T-011
DIAMOND F-581

EKIL - 6003



MITSUBISHI H3T021
DIAMOND F-693
FORD F32Z-12029-AA
MAZDA MA619849
FORD PROBE 93-94
MAZDA 92-94

EKIL - 6004



MITSUBISHI H3T022
DIAMOND F-694
FORD PROBE 93-95
MAZDA MX6 90-92 93-95


EKIL - 6005



MITSUBISHI H3T03975
NISSAN 0 040 170 689



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 6006



mitsubishi H3T03371
DIAMOND F-734

EKIL - 6007



MITSUBISHI H3T03273 , H3T030
NISSAN 0 040 170 689

EKIL - 6008



MITSUBISHI H3T03071A, H3T030
DIAMOND F-747

EKIL - 6013



KIA 27301-02700, 27301-02701



EKIL - 6014



HYUNDAI 27301-02100

EKIL - 6015



HYUNDAI 27301-23003
BERU 0040100267
BOSCH 0986221008

EKIL - 7001



CHAMPION BAE 403B
FIAT 46777286,55180004
MARELLI BAE 403B
LUCAS DMB858
BERU 0040100320
BOSCH 0986 221 042

EKIL - 7002



FIAT 46777288
ALFAROMEIO 46777288
CHAMPION BAE 403C
MAGNETI MARELLI BAE 403C
LUCAS DMB861
BOSCH 0986221043
BERU 0040100322

EKIL - 7003




ROVER NEC100730; NEC100730L
LAND ROVER
NEC000120; NEC000120L
BERU 004 100 501 0000
LUCAS DMB821
ERA 880191

EKIL - 7004



ROVER NEC000130; NEC100870
BERU 0040 100 502 0000
LUCAS DMB947
BREMI 20194



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 7005



BOSCH 0221504 014
BERU 0040100311; ZS311
FIAT 46467542
LAFA ROMEO 46467542
LANCIA KAPPA,FIAT,BRAVO,COUPE
LUCAS DMB864

EKIL - 7005A



BOSCH 1220703032, 0221504021

EKIL - 7006



TOYOTA
 90080-19017, 90080-19018,
 90080-19019
BOSCH
 0221504016, 0221504020, 1220703021
LUCAS DMB944

EKIL - 7006A



BOSCH 0221604008
BERU 0040102019 ZSE 019
VOLVO 30713416 4 PINS

EKIL - 7006B



BOSCH 0 221 604 010
VOLVO 30713417, 8677837

EKIL - 7007



BOSCH 0221504460
BERU 0040100321
FIAT 46777287,46776830,60740304
LUCAS DMB909
MARELLI BAE403D

EKIL - 7008



LAND ROVER NEC000070L , NEC000110L
ROVER NEC000070 , NEC000110
BERU ZS068, 0040100068
LUCAS DMB901
CHAMPION BAE403H

EKIL - 7009



LOTUS 77250002

EKIL - 7010




HYUNDAI 27300-85010 10E2702

EKIL - 7011



DENSO 6529003-6002



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 7012



HONDA 30521-PWA-003 UF-374
HITACHI: CM11-108
HONDA CIVIC JAZZ HYBRID FIT 1.3

EKIL - 7013



HONDA 30520-PWA-003 UF-373
HITACHI: CM11-109
HONDA CIVIC JAZZ HYBRID FIT 1.3

EKIL - 7014



HONDA 30520-PWC-003
HITACHI: CM11-110
HONDA FIT 1.5 HONDA CITY

EKIL - 7014A



HONDA
30520RB0003, 30520RB0013,
30520RB0S01, C1664
HONDA FIT 1.5
HONDA CITY 30520RB0S01, C1664

EKIL - 7015



HONDA 30520-PHM-003

EKIL - 7016



VOLVO 1275602 12756020, 12756029,
WELLS C1259 UF-365

EKIL - 7017



VOLVO
3531300 , 1275971 12759710, 12759718,
35313006, 91356899, 91467761
STANDARD UF167

EKIL - 7018



FORD 6485688, 91XF-12029-AA,
91XF-12029-BA
BOSCH 0221505423

EKIL - 7019



MAZDA :
L3G2-18-100A
6M8G-12A366
UF-540
3PION


EKIL - 7019A



FORD
6E5G-12A366, 029700-8391
2PION



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 7019B



MAZDA :

LEB6-18-100A

LEB6-18-100B

UF-541

3PION

EKIL - 7020



HONDA

30520-RBO-003

EKIL - 7021



BOSCH

0 221 504 001

BENZ

A000 158 72 03 CL500 CL600 E420 S420

S500 S600 SL500 SL600

EKIL - 7022



BENZ :

000 150 17 80; 000-150-28-80 UF-536

Mercedes-Benz C230 (02)

Mercedes-Benz SLK230 (04-01

BOBINA MERCEDES BENZ

SLK230 01-04

EKIL - 7023



ACOELCO

12578224 099700-0850 7426A

BERU

0 040 172 619 UF491

EKIL - 7024



BOSCH: 0221504026

FIAT 55214926

ALFA ROMEO 55214926

EKIL - 8001



BOSCH F000 ZS0 212

BERU 0040100281

DENSO 0297006700

MAZDA 88SF-1202-AA, 1E0518100, ZZMO-18-100,FSD718100

FORD 19017116,1649067,6503279,

1018139,1067601,1075786, 6077429,

88SF-12029-A1A,6181956,

88SF-12029-A1A,88SF-12029-A2A,

88SF-12029-AA ,F5RZ-12029-C, EDG43, DG

435 ,928F-12024DA,EDG42,

F5LU-12029-AA, F5LY-12029-A,

EKIL - 8001A



FORD

6181956,6503277,6503278,

6503279,6503280,6823318,

6860288,1008886,1008887,1018139,

FORD

USA 938F-12024-DA, 928F-12029-CA

MAZDA

1E0518100, 1E0518100A,

FSD718100,ZZMO18100 ZZM018100,

18E0518100, 18E0518100A

BERU 0040100239

EKIL - 8002



KIA 0K011-18-100

CITROEN / PEUGEOT 597053

Alfa Romeo

60558152,60809606,76487970

FIAT 60809606 7648797

VW 0489051051

HONDA

30520-PDF-E01 30520-PDF-E00

LAND ROVER ERR6045 ERR6566

RENAULT 6000581617 ,

LUCAS DMB300

BOSCH 0221503407

EKIL - 8002A



BOSCH F000ZS0204

GM


93248876, 93261953

OPEL 93261953

CHEVROLET 93261953



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8002B



BOSCH F000ZS0206
F000ZS0207
FIAT 46752948
FACET 9.6316

EKIL - 8002C



BOSCH 21113745010, 21113705010
MIT SUBISHI 9311600
LADA F000ZS0211
BERU 0040100234

EKIL - 8002D



BOSCH 0221503457
ALFA ROMEO 60558152,60809606,
7648797,76487970,60586072
CITROEN/PEUGOT 597053
FIAT 7648797,60558152,60809606
VW 0489051050,0489051051
LAND ROVER ERR6045,ERR6566
FERARI 1 34386
HONDA 30520-PDF-E01
KIA 05011-18-100,OK011-18-100
LUCAS DMB301
SMP 12637

EKIL - 8002E



BOSCH F000 ZS0205

EKIL - 8002F



VW/AUDI 026905105
BOSCH F000ZS0213

EKIL - 8002G



BOSCH F000 ZS0215
CHEVROLET 93312956
Chervolet Meriva 1.8
Fait: IDEA 1.8 PALIO 1.8

EKIL - 8003



MARSHALL ME 85-01

EKIL - 8004



ISUZU 8-01101-038-0,
8-01104-038-0
GM 1104038,10450424,10490192
OPEL 1208051,96350585,380017,
88921374, 1E01,E586A,
LUCAS DWB855
BERU 0040102025
OPEL FRONTERA 2.2i 16V 09/98
LEGANZA 2.2i 16V 09/98
DAEWOO LANOS 1.3i 04/97

EKIL - 8004A




DELPHI 19005270
DAEWOO 19005270

EKIL - 8004B



GM 96253555
DAEWOO 19005262
96253555
93363483
DELPHI 19005236
CHERROLET 93363483
ISUZU 8-01104-039-0
LUCAS DMB928 3 PINS


Ignition Coil
Cluster Ionizer
Solenoid
Auto Parts
EKIL - 8005


ISUZU 8-01101-038-0,8-01104-038-0
GM 1104038, 10450424, 10490192
OPEL 1208051
DAEWOO 96350585, 380017, 1E01
DAEWOO
 LANOS 1.3i 04/97 LUCAS DMB855
OPEL FRONTERA 2.2i 16V 09/98
LEGANZA 2.2i 16V 09/98

EKIL - 8005A


FORD 6V87QE-33705010A
 6V87QE-3705010B

EKIL - 8006


RENAULT 7700274008,
 6001543604
SAGEM 2526151A
NISSAN 22448-00QAC LUCAS
 DMB408
BREMI 11720
BOSCH F000ZS0221

EKIL - 8006A


RENAULT 7700274008
VALEO 245105
NISSAN 22448-00QAC
DACIA 6001543604
BERU 0040100354

EKIL - 8006B


RENAULT 7700872449,7700864624,
 7700872834,7700873701,
SAGEM 2 526 078 A, 2 526 078 B
VALEO 245 079
BREMI 11719
FEBI BILSLEIN 21525

EKIL - 8006C


Renault 8200141149
SAGEM 2526078B
LUCAS DMB883
BERU 0040100345

EKIL - 8007


FORD 1075786,1319788,1119835,1130402,
 1067601,988F-12029-AB, 988F-12029-AC,
 1S7G-12029-AB,1S7G-12029-AC, 1317972,
 1619343, 988F-12029-AD, 988F-12257-
 AB,98BF-12024-AB, 988F-12023-AC
MAZDA YF09-18-10X,1E0518100B, C201-18-
 100,1E041810X,
VOVLO 30735759
MARELLI 060801005010,BAE680C
Bosch 0221503490
BERU 0040100350

EKIL - 8007A



MAZDA L813-18-100

EKIL - 8007B


FORD 1F2U-12029-AC, 1F2Z-12029-AC,
 DG485,19017114 , 6630365
 GY07-18-100, XS2Z-12029-AC
 XS2Z-12029-AA,AJ03-18-100

EKIL - 8009


LADA
 2112-3705010-02
 2112-3705010-04



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8009A



LADA
2112-3705011-02
old type

EKIL - 8010



Chrysler 4557468,5296670,4609080,
4671025
FORD M04557468, M04777667,
E8BZ-12029-B, E8BZ-12029-A
BERU 0040102027 ZSE027

EKIL - 8011



DOAMOND 22433-AA400
BMW 12137510738
CHRYSLER
5269670 M0477667 M0477667
MITSUBISHI MD52696760 ,M04557468
M05269670
LUCAS DMB962

EKIL - 8011A



SUBARU 22433AA410, 22433AA570
22433AA41A, 22433AA418
STANDARD UF240
With ignition module

EKIL - 8012



CRYSLER
53006565, 4848841AA , 88921319, C531
DODGE TRUCKS 1997-2003
STANDARD
UF-121 DODGE TRUCK 94-96

EKIL - 8012A



CRYSLER 4443971, 88921253
C516
STANDARD UF-53

EKIL - 8013



CHRYSLER
5269670, 56032521,
M05269670,56032521AB
CHRYSLER 2001
DODGE 1997-2001
JEEP 2002

EKIL - 8014



VW
078905104 078905101 078905101A
BERU ZSE007

EKIL - 8015




BERU 0 040 100 029
CHAMPION BAE 920 A ,BAE 920 AX
FIAT/LANCIA 46480361 ,46446039,
46472440,7789346,
MARELLI 060792001010
LUCAS DMB811
BOSCH 0986221003

EKIL - 8016



FIAT 46446039, 46472440 ,46480361
7789346, BAE920AX
MARELLI 60792001,920AX
BERU 0040100058
FIAT Bravo, Marea



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8017



BOSCH

0221 503 012 ,0221 503035
F300-116246

BERU 00040100297

BENZ

0001587303 0001587803
A0001587803 A0001587303

EKIL - 8030



VW 032905106, 032905106B,
311740 ,032905106D
SEAT 032905106
SKODA 032905106

EKIL - 8030A



VW

032905106, 032905106B

SEAT 032905106B

SKODA 032905106

EKIL - 8030M



VW 032905106,032905106B
032905106D

AUDI 0221603006,0221603009,
0221603010, 0221603449

SEAT 032905106 032905106D

SKODA 032905106 032905106B

BERU 0040402003

EKIL - 8031



HYUNDAI

27301-02600

BOSCH

0986221005

BERU

0040100266

LUCAS

DMB935

ATDS

1.0L 4CIL 00-03

EKIL - 8031A



HYUNDAI

27301-23700

KIA

27301-23700

EKIL - 8031B



KIA

5WY2829A

IKCO

0040100515

BERU

0040100515

PEUGEOT

ROA

EKIL - 8031C



KIA

5WY2809A

BERU

0040100513

EKIL - 8031D




HYUNDAI 27301-23900

EKIL - 8031E



HYUNDAI 27301-02630



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8031F



HYUNDAI 27301-03010

EKIL - 8031R



CHRYSLER

MD184230 MD158409 MD334558
MD152648

MITSUBISHI

MD179787 MD184230 MD192126
MD310298 MD163599

DIAMOND

F-608 F-648

EKIL - 8032



LUCAS DMB971
LAND ROVER ERR6269

EKIL - 8032A



LUCAS DMB971
LAND ROVER ERR6269

EKIL - 8032B



HYUNDAI 27301-37100
BOSCH 0986221020
BERU 0040100269

EKIL - 8032C



GM 96453420
DAEWOO 96453420
CHEVROLET 96453420
DAEWOO Nubira 1.6l 16V

EKIL - 8032D



KIA 27301-26600
HYUNDAI 27301-26600

EKIL - 8032E



HYUNDAI 27310-22610

EKIL - 8032F




HYUNDAI 27310-37120
HYUNDAI SANTA FE 04-02
HYUNDAI TIBURON 04-03

EKIL - 8033



KIA OK30E-18-10X



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8034



HYUNDAI 27301-22040 , 27301-22050
BERU 0040100264
BOSCH 0986221004

EKIL - 8034A



HYUNDAI 2730126080
UF243

EKIL - 8035



TOYOTA 90919-02218,
90080-19008, 90919-02217, 90919-02220,
91919-02224, 90919-02226, 90080-
19007

EKIL - 8035A



TOYOTA 90919-02224

EKIL - 8035B



SUZUKI 33400-64G00
SUZUKI ESTEEM GLX1998 ,
GI1998

EKIL - 8035C



TOYOTA 90919-02221

EKIL - 8035D



TOYOTA 90919-02222

EKIL - 8036



BERU : ZS270
BOSCH : 0986221021
HYUNDAI : 27301-37120
27301-37110
HYUNDAI : SANTAFE(04-02)
HYUNDAI : TIBURON(04-03)

EKIL - 8036B



HYUNDAI : 27301-37120


EKIL - 8036C



HYUNDAI : 27301-02600 IC-83



SZ-H001



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8036A



HYUNDAI 27310-37140
HYUNDAI SANTAFE (04-02)
HYUNDAI TIBURON (04-03)

EKIL - 8037



BOSCH IK-021-12V
DIAMOND FIMC-021A1
MITSUBISHI MD314583
(BLACK CONNERTOR)

EKIL - 8037A



BOSCH IK-020-12V
DIAMOND FIMC-020A1
MITSUBISHI MD 314582
(WHITE CONNERTOR)

EKIL - 8038



MAZDA : E578A 88921326
BPE8-18-10XA
STANDARD UF-258
MAZDA MIATA(1994-1995)
MAZDA MX5(1993-1995)
4 PINS

EKIL - 8038A




FORD : FP39-18-10XC ,
FP39-18-10XD , FPY2-18-10X
HANSHIN DSC-550, EP19-18-18X ,
EP-18-10XD, 88921326BPE8-18XA
BPE8-19-10XC
3 PINS

EKIL - 8039A



KIA OK30E-18-10X

EKIL - 8039B



HYUNDAI : 27301-33020

EKIL - 8039C



HYUNDAI : 27301-23500
27301-23510

EKIL - 8040




CITROEN 597048, 597060,
96074054
FIAT 9607405480, 9607405482,
9622889780
PEUGEOT 597048, 597070
SAGEM 2526040A
VALEO 245040, CD331, 2526037A
ROVER 279115210104
PEUGEOT 106, 205, 306, 309,
405, 406

EKIL - 8040A



DUCELLIER 2526055
GM 90458250
OPEL 1208071
SAGEM 2526055A
SIMENS 5WK 90611
LUCAS DMB800
VALEO 245057, CD440,
2526055, 2526055A
BERU 0040100344



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8040B



BOSCH 0221503011
GM-MOTORS 90506102
OPEL 1208076
LUCAS DMB824
ERA 880199

EKIL - 8040C



PEUGEOT 597049
CITROEN 597049 , 96062288 ,
 9616597080
ROVER GCL204
VALEO 245041
BERU 0040100231
DUCELLIER 2526035A
LUCAS DMB201
BOSCH 0221503006, 0221503024

EKIL - 8041



BOSCH 0221503465
CHERY A11-3705110EA

EKIL - 8042



BYD 573614034

EKIL - 8042A



BOSCH F000ZS0235
FIAT 55230507 5523050
FIAT 55226876

EKIL - 8046



BOSCH 0221503010
OPEL 1208007, 90511450,
 90492255
LUCAS DMB848

EKIL - 8046A



OPEL 1208075
GM 90541062 , 90563160 ,
 D598
BOSCH 0221503017
BERU 0040100306 , ZS306
BREMI 20179
LUCAS DMB 849
STANDARD UF-379

EKIL - 8047



BOSCH 92099894
 Chevorlet Sail 03

EKIL - 8048




BOSCH 0221503485
FORD 4M5G12029ZA, 4M5G12029ZB
FORD FOCUS 1350562, 1459278
BREMI 20176
LUCAS DMB897
MAZDA C401-18100-A
VOLVO 30731416, 30731419,
 31216444, 31216444-AA

EKIL - 8048A



BOSCH 0221503490, 0221503491
 988F-12029-AD, 988F-12024-AB, 988F-
 10029-BA, 988F-12029-BA, IS7G-12029-
 AC, 1066102, 1067601, 1075786,
 1317972, 1619343 YM2F-12029-AB,
 YM2F-12024-AD
MAZDA 1E031810X,
 C201-18-100A,
 YF09 18 10X
VOLVO 30735759
MARELLI BAE 680C



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8048B



BOSCH 0221 503487
FORD 1350567 / 1458400,
457G12029AA/AB

EKIL - 8049



SUBARU 22433-AA570, 22443-AA50A

EKIL - 8050



PONTIAC 1103872, 1103905,
D553 D547
OPEL 1208063, 10457075
LUCAS DMB822
BERU 0040102026, ZSE026
MARELLI 940038528
940038528010

EKIL - 8051



PEUGEOT 597072, 597074,
9628158580, 596319
PEUGEOT 206, 106, 306, 307
CITROEN 597072, 597074,
9628158580, 96246755,
96281585
SAGEM 2526117A
VALEO 245109
LUCAS DMB812
BOSCH 0986221034

EKIL - 8051A



PEUGEOT 596319, 597078,
597079, 96358649,
2526208A, 2256208,
9635864980,
9635884880
LUCAS DMB813
BOSCH 0986221035

EKIL - 8052



RENAULT 8200051128,
8200025256,
8200084401
NISSAN 22448-00QAD
PEUGEOT 597083
BOSCH 0986221036
(3 MOUNTING HOLES)
(The length of 4 cables are
different)

EKIL - 8052A



LUCAS DMB903
RENAULT 8200051128,
8200360911,
8200702693
NISSAN 22448-00QAF
(4 MOUNTING HOLES)
(THE LENGTHS OF 4 CABLES ARE SAME)

EKIL - 8052B



RENAULT 8200702693
H8200734204
(4 PINS)

EKIL - 8053




PEUGEOT 597057
SAGEM 2526086(A)
CITROEN 0000597057
BERU 0040100343
PERGEOT 406 605

EKIL - 8054



VW/AUDI 06A905097,
06A905104
LUCAS DMB852
BREMI 20129
TEMIC 307243
BERU 0040102029
NEW BEETLE 2.0 L
SANTANA 3000



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8055



PEUGEOT / CITROEN

597056, 96213086, 9621308680
SAGEM 2526087, 2528087A
VALEO 245086
LUCAS DMB854
BERU 0040100241, ZS241
PEUGEOT 106 1.6L
CITROEN sexo 1.6VTS

EKIL - 8055A



PEUGEOT / CITROEN

597080, 597099, 96363378
SAGEM 9636337880, 2526182A
VALEO 245095, 96363378
PEUGEOT 307 1.6L
BERU 0040102045

EKIL - 8056



CITROEN-PEUGEOT

597075, 597098, 94632641,
 96341314 , 96632641, 9634131480
FIAT 9663264180, 9634131380,
 9634131490
VALEO 245098, 2526118, 2526118A
PEUGEOT 307 206 407 408
 607 807
LUCAS DMB866
BERU 0040100348

EKIL - 8057



PEUGEOT 597073, 5970A4

CITROEN 96292106, 9629210680
VALEO 2526119A
LUCAS DMB869
BERU 0040100349

EKIL - 8057A



SAGEM 2526059A

PEUGEOT 597051, 5970A5
CITROEN 96211048
VALEO 245046
BERU 0040100256

EKIL - 8058



PEUGEOT/CITROEN 597084

CITROEN C4,C8
PEUGEOT 307,406,407,607,807
LUCAS DMB875
STANDARD 12756
VALEO 245100 2526131A
BERU 0040100351

EKIL - 8059



CITROEN/PEUGEOT 597087

CITROEN C4,C5
PEUGEOT 307,407,807
LUCAS DMB917
VALEO 21597716-4, 245101
BERU 0040100352

EKIL - 8060



OPEL 1208307

GM 19005212, 47905104,
LUCAS DMB816
MARELLI 060801008010,
 BAE608F
BERU 0040100259, ZS259
BOSCH 0986221039

EKIL - 8060A



Chevrolet /Daewoo 96415010
GM 96415010


EKIL - 8061



GM 09119567, 90536194
OPEL 1208008
SAAB 9119567
VALEO 2526116A
LUCAS DMB817
BERU 0040100342



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8062



BOSCH 0221503033, 0221503034
MERCEDES-BENZ 0001501380,
 A0001501380
LUCAS DMB819

EKIL - 8063



GM 90543059, 90532618
OPEL 1208306
BOSCH 0221503014
LUCAS DMB815
BERU 0040100358

EKIL - 8063A



GM 93180806
BOSCH 0221503471
OPEL 24420622, 1208028
BERU 0040100359

EKIL - 8064



BOSCH 0221503015
OPEL 1208012, 90543253,
 90560110
LUCAS DMB814

EKIL - 8064A



GM 93177212
OPEL 1208020 , 24420584
BERU 0040100338, ZS338
BOSCH 0221503472
LUCAS DMB880

EKIL - 8065



OPEL 1208021
GM 10458316, 1104082
DELPHI CE20009-12B1
FIAT / ALFAROMEIO
 71739725, 71744369
LUCAS DMB939 1.6 1.8 1.6T
 (6 PINS)

EKIL - 8065A



CHEVROLET 55570160
CRUZE 1.6
 OE NO. 96476979 (7 PINS)

EKIL - 8065C



CHEVROLET 55571790
CRUZE 1.6T (7 PINS)

EKIL - 8065D



DELPHI 19005358, 25186687
CHEVROLET 96476983
GM 55561655
OPEL 1208086 (7 PINS)


EKIL - 8065E



DELPHI 28326927
GM 55584404
OPEL 1208098 (7 PINS)



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8065F



CHEVROLET 55584745
DELPHI CEO1841-11BI (7 PINS)

EKIL - 8065G



CHEVROLET 55585539
DELPHI CEO1840-11BI
CRUZE 1.6 (7 PINS)

EKIL - 8066



CITROEN / PEUGEOT
597085, 9651710680,
LUCAS DMB986
CITROEN C2 1.4, C3 1.4, C4 1.4
PEUGEOT 206 1.4, 207 1.4,
307 1.4, 6 PINS

EKIL - 8067B



BOSCH 0221503026
OPEL 1208209, 90584336,
9118114
GM 9118114

EKIL - 8067G



BOSCH 0221503027
GM 9118115
OPEL 1208210, 90584337,
9118115

EKIL - 8068



GM 12580537
OPEL 120826
IC -47

EKIL - 8069



SAAB 55561132, 9178955,
SAAB 9000, GM900,
(RED BRACKET) 10 PINS

EKIL - 8069A



SAAB 55559955, 55562588
9197559
BLACK BRACKET 10 PNS

EKIL - 8070




SAAB : 55561133.90790573
1999-2003 SAAB 95 9-5 3.0L
V6 TURBO
Standard 12495 smp uf420

EKIL - 8071



VW/AUDI 047905104A,
047905104B
CHAMPION BAE961AE
ZSE040 4 PIN



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8072



AUDI/VW 047905104
CHAMPION BAE960AE
SKODA FELICIA 4 PINS

EKIL - 8074



OPEL 1208094
OPEL 1208091
SKODA FELICIA 4 PINS

EKIL - 8075



Bosch 0221 503 469
0221 503 467
Opel 9153250 93172030
Fiat 71739702

EKIL - 8076



Bosch 0221 503 468
0221 503 467
Opel 90424480, 9198834
6235037

EKIL - 8077



OPEL 1208096
OPEL 1208092

EKIL - 8078



KIA TUS 5WY2847A
PEUGEOT 206 405
IRANI : 1KCO/RUNNA

EKIL - 8079



CHRYSLER/DODGE/JEEP 56041476AA
JEEP CHEROKEE 00-01 6 CIL. 4.0 L. **GRAND CHEROKEE** 00-04 6 CIL. 4.0 L.
WRANGLER 01-06 6 CIL. 4.0 L.

EKIL - 8079A



CHRYSLER/DODGE/JEEP 56041019
JEEP
GRAND CHEROKEE 1999 6 CIL. 4.0 L

EKIL - 8101



FORD 6383157, E9DF12029AA
E9DZ12029A, F0TZ12029 A, F1DZ12029A,
F3DU12029AA, F3DZ12029A,
F82U12029AA, 90TF12029A1A, 19017113,
F-508, DG-455, DG-459, DGE-446,
MAZDA KLG4-18-100A,
ZZL0-18-100, ZZM7-18-100
DENSO 19017113


EKIL - 8102



FORD 919F-12029-AA,
E9SF-12029-AA, F5SU-12029-AA, E9SZ-
12029-A, 19017114, F-509, 6630365,
6958305
MOTORCRAFT DG-440
DENSO 029 700 6760, 029 700 7180
JAGUAR LNA 1508AA
LUCAS DMB752



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 8120



CHRYSLER 4443971, 4643177,
52333140, 525673
GM 88921253

EKIL - 8121



BOSCH 9220061800
FORD 94DA-12029-AC

EKIL - 8122



CRYSLER
56029098AA, 56032520,
88921268 , 56032520AE, 88921319 ,
C531
STANDARD UF-305
STANDARD UF-412

EKIL - 8123



CHRYSLER 4609140AB
88921412, UF260
CARVAN, TOWN&COUNTRY VOYAGER
YEAR 1999-2000

EKIL - 8124



CHEVROLET / DAEWOO 96291054
CHEVROLET MATIZ
(M200,W250)0.8
4 PINS

EKIL - 8125



GMI 12587153 , H6T40171ZC 5114
AA 145 , D516A, UF434

EKIL - 9001



VW/AUDI
06B905105, 06B905115
06B905115B, 06B905115E
HITACHI CMIT-201
AUDI A3 A6 A8 TT
LUCAS DMB820

EKIL - 9002



AUDI/VW 06A905115, 06A905115A,
06A905115B, 06A905115C, 06A905115D
06B905115G, 06B905115H,
06B905115M, 06B905115N,
06B905115J, 06B905115L, 06B905115R
BREMI 12496
BOSCH 0986221024
BERU 0040102043

EKIL - 9002A



AUDI/VW
07K905715A, 07K905715B,
07K905715C, 07K905715D,
07K905715E, 07K905715F,
06F 905 115, 06F 905 115A
06F 905 115B, 06F 905 115C 06F
905 115D, 06F 905 115E 06F 905
115F


EKIL - 9002B



VW
07C 905 115D, 07C 905 115J,
07C 905 115H, 07C 905 115F,
07C 905 115E, 07C 905 115C, 06F 905
115D, 06F 905 115E, 06F 905 115F,



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9002C



AUDI/VW

077905115, 077905115C,
077905115E, 077905115F,
077905115H, 077905115Q
077905115T, 077905115K
UF418

EKIL - 9002D



AUDI/VW

06C905 115, 06C 905 115A,
06C 905 115B, 06C 905 115E,
06C 905 115F, 06C 905 115G ,
06C 905 115H, 06C 905 115K,
06C 905 115L, 06C 905 115M,
UF483

EKIL - 9002E



AUDI/VW

06D905 115, 06D 905 115A,
905 115J, 06E 905 115,
06E 905 115A, 06E 905 115B,
06E 905 115C, 06E 905 115D,
06E 905 115E, 06E 905 115J

06D

EKIL - 9004



TOYOTA
DENSO

90919-02212
0297007951

EKIL - 9004A



TOYOTA 90919-02213

EKIL - 9004B



TOYOTA 90919-02215

EKIL - 9005



FORD

F7TZ-12029-AB, IL2U-12029-AA, IL2Z-
12029-AA, F7TZ-12A366-BA, F7TZ-
12029-BA, F7TZ-12029-CC, F7TZ-12029-
CA, F7TZ-12A366-AB, 3W7Z-12029-AA,
DG508

FORD

98-2000, DG491, DG467, DG472

LINCOLN 98-2000

MERCURY 98-2000

EKIL - 9005A



FORD

BA-12A336-A
3R2U-12A366-AA

EKIL - 9005B




FORD 4L7E-12A366-AA
1F3Z-12029-AA
4L7Z-12029-AA

EKIL - 9005C



FORD 3L3E-12A366-CA
6B1424, 140033



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9005D



FORD 4W5G-12A366-BA,
4M5G-12A366-BB,
4M5G-12A366-BC

EKIL - 9005E



FORD 2M2E-12A366AC,
2M2E-12029AC,
MOTORCRAFT DG-513
STANDARD UF-406 APPLICATION :
Ford Taurus (06-05)
Mazda MPV (06-02)
Mercury Sable (05)

EKIL - 9005F



FORD 2M4Z-12029-BO
MOTORCRAFT DG515, FD506
XW4V-12A366-BB
APPLICATION:
Ford Thunderbird (05-02)
Lincoln Ls (06-00)
Jaguar S-type (03-00)

EKIL - 9005G



FORD 2M4Z-12029-AA,
2W4Z-12029-AB,
2W4Z-12029-AC,
2W4Z-12A366-BD
MOTORCRAFT DG-517, FD496, F569
JAGUAR C2S42751

EKIL - 9005H



FORD
DG-465, F6DU, 12A366 AB,
F6DZ-12029A, F6DZ-12029AA,
F6DZ-129029EA, F-522,
88921347
UF-162

EKIL - 9006



SUZUKI 33410-77E10
33410-77E11

EKIL - 9006M



SUZUKI 33410-77E20
33410-77E21
VITARA V6

EKIL - 9007



BOSCH 0221503465
MITSUBISHI MD362903,
89057964,
HAFEI MD362903

EKIL - 9007A



DENSO 099700-048
C1200C, UF280
HYUNDAI 9C19-0370
SUZUKI 88921403, E529A
MITSUBISHI MD362903, 4G18
PROTON WJ-903-ND


EKIL - 9007B



FORD / FIERRA ZL01-18-100
FORD FOTZ 12029A
MAZDA ZZY1-18-100
BOSCH F005X11773



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9007C



mitsubishi MD325048, MD362907
CHRYSLER MD325048, MD362907

EKIL - 9007D



MAZDA FFY1-18-100, FP85-15-100C,
FP85-18-100

EKIL - 9007E



SUZUKI
33410-77E01, 33400-65G02,
33400-65G01, 33410-65G00
HYUNDAI 9C19-0370
mitsubishi S37000067PG
FIAT 71742420

EKIL - 9007F



SUZUKI 33410-66D01,
30020581, 88921408

EKIL - 9007G



mitsubishi 33400-62J00

EKIL - 9007H



SUZUKI 33410-66D10
SUZUKI 33410-66D00

EKIL - 9007L



mitsubishi
MD372045 , MD372035 UF-525

EKIL - 9008



TOYOTA 19500-B0010

EKIL - 9008A




TOYOTA 19500-87101
DIAMOND FL0080

EKIL - 9008B



DENSO : 099700-048
mitsubishi MD362903, 4G18
PROTON : WJ-903-ND



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9008C



DAIHATSU 90048-52130
DIAMOND FK0099

EKIL - 9008D
(EKIL-3094)



DAIHATSU 19500-87102

EKIL - 9009
(EKIL-9010)



NISSAN 22448-00QAA,
22448-00QAC, 22448-00QAE,
22448-6N011
OPEL 91159996, 4408389 RENAULT
7700107177, 7700113357, 7700113357A,
7700875000, 8200154186, 8200154186A,
8200208611, 8200380267
VALEO 21603121-9, 245104 LUCAS
DMB804
SAGEM 21595273-2, 2 526 180 A
BOSCH 0986221001

EKIL - 9009A
(EKIL-9009)



RENAULT 7700107177, 7700113357,
7700113357A, 7700875000,
SAGEM 21595273-2
Renault 8200568671

EKIL - 9009B
(EKIL-9011)



GM 91159920, 91159996, 93161188
93161948
BOSCH 0986221001
BERU 0040100052 RENAULT
7700875000, 7700107177,
7700113357, 8200154186, 8200405098,
8200568671, 8200208611
OPEL 4408389, 4413233, 91159996
NISSAN 22448-00QAA, 22448-00QAB,
22448-00QAC, 22448-00QAE, 22448-
00QAH

EKIL - 9010B



NISSAN 22448-2Y000
22448-2Y001 22448-2Y010
NISSAN MAXIMA V6 2000 20001
INFINITI 130 V6 2000 20001

EKIL - 9010C



NISSAN 22448-2Y005, 22448-2Y006
22448-2Y007 22448-Z7015 INFINITI 130
V60 2000 20001 NISSAN **MAXIMAM** V6
2000 2001 MITUSBISHI H6T10271A
UF-332/UF-363

EKIL - 9010D



NISSAN 22448-3H000

EKIL - 9010E



NISSAN 22448-4W001
22448-4W000
uf-328


EKIL - 9010F



NISSAN 22448-4W011,
22448-4W010



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9011
(EKIL-9048)



DIAMOND 90048-52126
DENSO 099700-0570

EKIL - 9011A
(EKIL-9047)



DENSO 099700-0581 099700-0340
SUZUKI 33400-7660 33400-76G0 **Suzuki**
33400-76G00

EKIL - 9011B
(EKIL-9013M)



GM 94859441, 94859442
TOYOTA 90919-02239, 90080-19015, 90919-T2002, 90080-19019, 90080-19017
PEUGEOT 597088
CITROEN 597088

EKIL - 9011C



TOYOTA 90919-02229

EKIL - 9012



PEUGEOT 597077, 597094
FIAT 9664401880 9633001580
PEUGEOT CITROEN 9633001580
PEUGEOT 406 607 407 807
RENAULT 9633001580
BERU 0040100347

EKIL - 9012A
(EKIL-9025A)



KIA OK24718 100A, OK24718 100A
OK13-18-100

EKIL - 9012B
(EKIL-9025)



KIA OK01318100, OK01318100

EKIL - 9013



BOSCH 0221504100
BMW 12137551260, 12131712219, 12137594935, 12137594936, 12137594937, 12137594938 1712219, 1712223, 7551260
BERU 0040100324 **PEUGEOT / CITROEN** 597064 597091
BREMI 20110
LUCAS DMB877

EKIL - 9013A




BMW 12137551049, 12137562744, 12137571643, 12137594937, 9008019025,
STANDARD UF506, UF571

EKIL - 9015



VW 036905715A, 036905715E, 036905715C, 036905715F, 036905715, 036905100A 036905100C, 036905100D
LUCAS DMB807
BOSCH 0986221023
BERU 0040102030



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9016



VW 022905100N,022905100A,
022905100D,022905100G,
022905100k
FORD 1120169 1673468 1252407
1331283 1362718
6M21-12029-AA
YM21-12029-AC
BERU 0040102063
LUCAS DMB910

EKIL - 9016A
(EKIL-9002)



VW 022905100,022905100B,
022905100E,022905100H,
022905100L,022905100P
022905100S,022905100T
VW 022905715
955 602 101 05
0 040 102 044

EKIL - 9017
(EKIL-9020)



LADA 12207 03202,
2112 3705010 10,
21120370501010
350023250, 050203050 **BOSCH**
0221504461

EKIL - 9017M



BOSCH 0221504473
LADA

EKIL - 9018
(EKIL-9023)



HYUNDAI 27301-23400,
0119-6-21278
CHAMPION BAE 400D

EKIL - 9018A



HYUNDAI 27301-26640
ELANTRA 1.6W (2006-2007)
YUEDONG 1.6W (2006-)
ACCENT 1.6W (2006-)
HYUNDAI 03220-10874

EKIL - 9018B



HYUNDAI 27301-26640
ELANTRA 1.6W (2006-2007)
YUEDONG 1.6W (2006-)
ACCENT 1.6W (2006-)
HYUNDAI 03220-10874

EKIL - 9019



FIAT LANCIA 46473849
HITACHI GE-215492,CM11-202
LUCAS DMB819
BERU 0040102020, ZSE020

EKIL - 9020



DENSO HYUNDAI 27301-3C000
KIA SORENTO 2008
STANDARD UF-546


EKIL - 9021
(EKIL-9049)



TOYOTA 90919-C2003, 90919-02252



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9022



ELIM

FIAT 46460582
HITACHI CM14-301A

EKIL - 9023



ELIM

HONDA 30520-P8E-A01,
30520-P8F-A01
30520-P8F-A02,
30520-RCA-A02

STANDARD UF-242

EKIL - 9023A



ELIM

HONDA 30520-R70-A01,

EKIL - 9024

(EKIL-9068)



ELIM

CHRYSLER 56028138AF,56028138AB
56028138AD

EKIL - 9025 (EKIL-9022)



ELIM

HYUNDAI 27301-37410

EKIL - 9026



ELIM

MAZDA N3H1-18-100

EKIL - 9027



ELIM

GM 12570553, 12558693, 23218007
CADILLAC ESCALADE (05-02)
CHERY AVALANCHE (06-02)
GMC ENVOY (04-03)
HUMMER H1(05)
STANDARD UF-271

EKIL - 9027C



ELIM

LAND ROVER LR002427 4603135 , 6H24-
12029-AA
JAGUAR LR002427
AUSTIN 4603135
AIRTEX 5C1736 : BWD E1090
STANDARD 12148 , UF-590

EKIL - 9028



ELIM

NISSAN 22448-ED800,
22448-ED800EP,
22448-CJ00A
RENAULT 7701065086
BERU 0040102506
BOSCH 0221604020 1220703040
STANDARD UF-591

EKIL - 9028A




ELIM

BOSCH 0221504030
RENAULT 8200699627



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9029
(EKIL-9031)



TOYOTA 90919-02237
TOYOTA TACOMA (04-00)

EKIL - 9030
(EKIL-9029)



TOYOTA 90919-02227
FIT LEXUS 1998-2009
TOYOTA 1998-2009

EKIL - 9031



BOSCH 0221604103
FIAT 46794782
ALFAROMEIO 46794782
(4 PINS)

EKIL - 9110
(EKIL-9032)



TOYOTA 90919-02247
90919-02248
90919-A2001
90919-C2001
90919-T2001

EKIL - 9111
(EKIL-9030)



TOYOTA 90080-19027,90919-02249
90919-02230
STANDARD UF-493

EKIL - 9113



TOYOTA 90080-19016,
90919-02234,
90919-02207,
1908046020
STANDARD UF-267

EKIL - 9115
(EKIL-9014)



TOYOTA 90919-02244,
90919-19023,
90919-02243,
90080-19016,
90080-19023
HYUNDAI 88921393
LUCAS DMB954
STANDARD UF-333

EKIL - 9116
(EKIL-9012)



TOYOTA 90919-02240, 90080-19021
LUCAS DMB902
STANDARD UF-316

EKIL - 9116A



TOYOTA 90919-02230


EKIL - 9117



HONDA 30520-PUK-A01
STANDARD UF400



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9117A (EKIL-9063)



HONDA 30520-PNA-007,
30520-PRA-007,
30520-RAA-007,
30520-RRA-007
STANDARD UF-311

EKIL - 9117B (EKIL-9069)



HONDA 30520-RNA-A01
DENSO 099700-102
STANDARD UF-582
HONDA Civic (09-06) 1.8L

EKIL - 9118 (EKIL-9035)



NISSAN 22448-4M500,
22448-4M50A
HITACHI CM11-205
MAZDA 1N10-18-100
BERU 0040102021
LUCAS DMB856
BOSCH 0986JG1211

EKIL - 9119



NISSAN 20181-CE121,19070-BZ040
DENSO JK099700-0990

EKIL - 9119A



TOYOTA 90919-02238
GM 88970216
STANDARD UF-314

EKIL - 9120 (EKIL-9052)



NISSAN 22448-8J115
NISSAN 350Z 2003-2006
INFINITI G35 2003-2004
INFINITI FX 35 2003-2005
STANDARD UF-349

EKIL - 9120A



NISSAN 22448-EA000
STANDARD UF-509
NISSAN FRONTIER (09-05)

EKIL - 9120B (EKIL-9053)



NISSAN 22448-6N015,22448-8U115
STANDARD UF-351
NISSAN SENTRA (06-02)

EKIL - 9120C (EKIL-9057)



NISSAN 22448-8H315, 22448-8H310,
22448-8H311, 22448-8H300
STANDARD UF-350
NISSAN ALTIMA (06-02)
NISSAN SENTRA (06-02)


EKIL - 9120D (EKIL-9056)



NISSAN 22448-7S015
STANDARD UF-510
INFINITI QX56 (07-04)
NISSAN ARMADA (07)
NISSAN PATHFINDER (04)
NISSAN TITAN (07-04)



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9120E



ELIM

NISSAN 22448-JA00C, 22448-ED000
22448-JA00A

EKIL - 9120F



ELIM

NISSAN 22448-JA10C
22448-JA10A
22448-JA11C
UF-550

EKIL - 9120M



ELIM

ZJ01-18-100
AIC 4501

EKIL - 9120G



ELIM

NISSAN 22448-AR215, 22433-AR215
STANDARD UF-482
INFINITI
NISSAN

EKIL - 9120N



ELIM

Nissan 22448-AR015

EKIL - 9120L



ELIM

NISSAN 22448-AL61C, 22433-AL61C
22448-AL615, 22433-AL615
STANDARD UF-401

EKIL - 9120J



ELIM

NISSAN 22448-ZE00C, C1672
22448-ZE00A
STANDARD UF-551

EKIL - 9121N



ELIM

CHRYSLER 56028394AD
CHRYSLER 56028394AC
STANDARD UF-505 UF-378
CHRYSLER 300 SERIES50
DODGE MAGNUM50

EKIL - 9122



ELIM

HYUNDAI 27301-38020
STANDARD UF-285
HYUNDAI SANTE FE(02-01)
HYUNDAI SONATA(05-99)
KIA OPTIMA(06-01)

EKIL - 9123




ELIM

SUZUKI 33400-76G30 (3 PINS)



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9123A



C2S 11480; C2S 7928; C2S42673;
XR8 22478
ZSE715 UF-435
JAGUAR

EKIL - 9124



CHRYSLER 04606869AB
HONDA 04606869AB
IC-190
UF-502
ZSE644

EKIL - 9124A



CHRYSLER 04606 824AB
IC-88
UF-557
ZSE653

EKIL - 9125



TOYOTA 90919-02246, 90080-19025
LEXUS ES330 2004-2006
LEXUS RX330 2004-2006
TOYOTA CAMRY 2004
TOYOTA HIGHLANDER 2004-2006
TOYOTA HIGHLANDER HYBRID 2006

EKIL - 9126



MITSUBISHI F6T56472

EKIL - 9126A



MITSUBISHI

EKIL - 9127



TOYOTA 90919-02214,
90919-02211, 88921328
STANDARD UF204

EKIL - 9128 (EKIL-9033)



BOSCH 0221604112
GM LACROSSE 12629037
OPEL 12583514, 12566569
FIAT 71753911

EKIL - 9128A




BUICK/CADILLAC 12590990
GM 12618542 12610626
UF-569 IC-287
DENSO 099700-1180

EKIL - 9129



SUZUKI 33400-65J00



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9130



TOYOTA 90919-02215
88921336, 9008019012, E588
STANDARD UF-155

EKIL - 9131



CHRYSLER 4609088AC, 4609088AD,
4609088AF

EKIL - 9131A



CHRYSLER
4609095AG; 4609095AH,
4609095AI, 04609095AC,
04609095AD, 04609095AF,
4609095AB, 4609095AC,
4609095AD, 4609095AE,
4609095AF

EKIL - 9132



TOYOTA 90919-02235

EKIL - 9133



TOYOTA 90919-A2004 90919-A2002
90919-02251

EKIL - 9134



KIA 27300-3F100

EKIL - 9135



HONDA 8-97136-325-0
8-97174-554-0
UF-245
BOBINA HONDA PASSPORT98-99

EKIL - 9136



SAAB 12787707 SAAB 9-3
MITSUBISHI H6T60271
HAS-004-05
SAAB SPORTS 2003-2010 1.8T 2.0T
PETROL ENGINE (B207)

EKIL - 9137



HONDA 30520-RNO-A01


EKIL - 9138



HONDA 30520-R40-007
DENSO 099700-147



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9138A



Factory Number
oe 30520pnc
STANDARO UF417
OE 30520-PNC-004

EKIL - 9139



SUBARU 22433-AA550

EKIL - 9139A



SUBARU 22433-AA540

EKIL - 9140



TOYOTA 90919-02250
90919-02256
90919A2003
90919A2005

EKIL - 9141



TOYOTA 90919-522F1

EKIL - 9142



Honda 30520P8EA00, 30520PGKA01
30520PVFA01, 30520RDJA01
Wells 5 C1016, 5C1633
C1460, C1576

EKIL - 9143
(EKIL-9142)



HYUNDAI 27301-2B000

EKIL - 9144



LADA 2112-3705010-11

EKIL - 9145



B.M.W 1 748 017, 748 018
12 12 1 748 017
12 13 1 748 018


EKIL - 9146



UF589
HONDA :1832A016



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9146A



MN-195805

EKIL - 9147



BYD F3

EKIL - 9148



HYUNDAI 27301-2B010

EKIL - 9148A



HYUNDAI 27301-2B100

EKIL - 9149



STANDARD UF-532 CHRY

EKIL - 9149A



CHRY MN195616

EKIL - 9150



FORD 6ESE-12A375-BA
6E5Z-12029-BA
MAZDA ZXD4-18-100
STANDARD UF-486

EKIL - 9151



STANDARD UF-504
CHRY 56029129AB
099700-1120

EKIL - 9152



JAGUAR 44430036
LHE1510AB
LUCAS 42533D 90002444
SUZUKI 33400-75F10
jaguar XJ6 /XJR 1994-1997(X300)


EKIL - 9153



TOYOTA 90919-02236



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9154



LAND POVER
4744015 4526466
6R83-12A366-AA
099700-1120

EKIL - 9155



GM 12596547
12612369
12619472
IC-280
UF-497

EKIL - 9156



Toyota.19070-B1020

EKIL - 9157



mitsubishi

MN187373; MR984160
UF-481

EKIL - 9158



VW 030 905 110B

EKIL - 9159



MAZDA FS1E-18-100

EKIL - 9160



Jaguar: Llca1510ab Standard;UF347
Wells:C1205
2 Pins

EKIL - 9161



Jaguar: LNE1510ab
LNE1510AB, XW93-12029-AB
Standard;UF415
4 Pins

EKIL - 9162



SUZUKI 33400-51K20
UF-634



EKIL - 9163



HYU/KIA : 27300-39050,
27300-39000
STANDARD UF-432



ELIM ELECTRONICS CORP.



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9164



Mitsubishi : MD363552
STANDARD UF-523

EKIL - 9164A



Mitsubishi : MD363552
STANDARD UF-523

EKIL - 9165



MER: 000 150 27 80 ,
000 1501980 000 1502680 ,
000 150 2780 07C 905 115 ,
07C 905 115C 07C 905 115D
19005267 , 68011844AA
STANDARD UF-535

EKIL - 9166



BOSCH 0 221 504 017
BERU ZS338
NISSAN 22448-1F700

EKIL - 9168



HONDA 30520-5A0F-A001
09977-535

EKIL - 9169



FOMOCO: AL3Z12029A

EKIL - 9170



FOMOCO: AL3Z12029B

EKIL - 9171



TOYOTA: 90919-02253

EKIL - 9172




7T4Z12029DA, 7T4E12A375EE,
C1686, CY0118100A, CY0118100Z02,
C1595, 5C1743, GN10237.IC633,
DG520
STANDARD UF-553

EKIL - 9172A



BR3Z12029A, C1802
MOTORCRAFT DG542



Ignition Coil

Cluster Ionizer

Solenoid

Auto Parts

EKIL - 9172B



FORD BL3Z12029C, DG548

EKIL - 9173



CHRYSLER/DODGE/JEEP 05149168AH
BOSCH 0221504 032

EKIL - 9174



CHRYSLER/DODGE/JEEP 05149199AA ,
5149199AA

EKIL - 9174A



CHRYSLER/DODGE/JEEP
05149049AB ;5149049AB ; 68078732AA

EKIL - 9175



HONDA:
8-19005-249-0 UF-251
NOTA: CILINDRO 1 al 5
HONDA
PASSPORT 00-02 3.2 L. 6 CIL.
ISUZU
AMIGO 2000 3.2 L. 6 CIL.
AXION 02-03 3.5 L. 6 CIL.
RODEO 00-04 3.2 L. 6 CIL.
RODEO SPORT 01-03 3.2 L. 6 CIL.
TROOPER 00-02 3.5 L. 6 CIL

EKIL - 9175A



HONDA:
8-19005-250-0; 8-19005-250-1
UF-252
NOTA: CILINDRO 6
HONDA
PASSPORT 00-02 3.2 L. 6 CIL.
ISUZU
AMIGO 2000 3.2 L. 6 CIL.
AXION 02-03 3.5 L. 6 CIL.
RODEO 00-04 3.2 L. 6 CIL.
RODEO SPORT 01-03 3.2 L. 6 CIL.
TROOPER 00-02 3.5 L. 6 CIL.

EKIL - 9010



NISSAN 22448-31U06,22448-31U16,
NISSAN 22448-31U05,22448-31U15
89057914,89057932 ,
NISSAN 1995-1997

EKIL - 9010A



NISSAN 22448-31U01,22448-31U00,
22448-31U11
NISSAN 1995-1997
BOSCH 0986JG1214